

Sets of taps

For ISO metric threads - Coarse pitch In high speed steel - HSS

FABC TOOLS







M

M



For cutting threads Ø 3 - 4 - 5 - 6 - 8 - 10 - 12 mm

With twist drills for pilot holes

In metal box (28 pieces)

in metal box (20 pieces)				
Consisting of:				
1 piece for each Ø		3 pcs. for each \emptyset		
2,5 - 3,3 - 4,2 - 5 - 6,75 - 8,5 - 10,25		3 - 4 - 5 - 6 - 8 - 10 - 12		
Code F 7949 2000	F 7949/2	Each €	> 1	

Empty box

	Code F 7949 3000	F 7040/3	Fach €	□ 1		

For cutting threads Ø 3 - 4 - 5 - 6 - 8 - 10 - 12 mm

In high strength synthetic resin box (23 pieces)

in riight strength synthetic resimbox (20 pieces)					
Consisting of:					
3 pcs. for each Ø	Size		ratchet tap wrenche size		
3 - 4 - 5 - 6 - 8 - 10 - 12	11	1½ 1			
Code F 7949 4000	7949/4		Each €	3 1	



With machine taps

For cutting threads Ø 3 - 4 - 5 - 6 - 8 - 10 - 12 mm

Consisting of:

7 taps DIN 376 for through holes from M3 to M12 with lead chamfer

7 taps DIN 371 for blind holes from M3 to M12* with 35° right-hand helix				
In synthetic resin box (14 pieces)				
Code F 7949 5000	F 7949/5	Each €	> 1	

^{*} M 12 = DIN 376




NORMEX° With machine taps

For cutting threads Ø 3 - 4 - 5 - 6 - 8 - 10 mm

In high strength synthetic resin box (6 pieces)

Version with 6 taps F 7830

For through holes and blind holes - 5-6 thread A chamfer





For through holes - Lead chamfer



Tap and die sets for cutting threads → F 5 pag. 556

